

GM Holden 3.6L V6 – CSC installation instructions

Ref: TN038

Issue date: Feb 2018

Issue number: 4

GMK-7744SMF

(Kit including replacement Single Mass Flywheel).

The two spacers and washer supplied in this kit must be fitted between the CSC (Concentric Slave Cylinder) and the transmission face to ensure correct clutch operation. Suitable bolts are also provided to compensate for this change.

Please refer to the below images for information relating to the positioning and correct orientation of these spacers.

