

# Fiat Pull Type Clutch Bearing Retainer Orientation

Ref: TN082

Issue date: Mar 2015

Issue number: 1

## CAUTION

The nylon retainer ring on the clutch release bearing in this kit must be correctly located to ensure proper clutch operation. If the retainer ring has shifted in transit, carefully push the retainer over the circlip into the groove as depicted in figure 2.

Please note that installation of the release bearing with the nylon retainer ring incorrectly located can in some cases result in sudden clutch engagement and the potential for **serious consequential damage**.

