

Hyundai Clutch Disc Correct Orientation

Ref: TN084

Issue date: June 2015

Issue number: 1

CAUTION

It is important to ensure that the 'raised' section of the clutch disc spline hub is facing the transmission as depicted below. Failure to orientate the disc correctly will result in a disengagement problem (unable to select gears) and/or damage to the clutch cover and flywheel.

