

Nissan Patrol Erratic Pedal Feel (Pedal Graunch)

Ref: TNL

Issue date: 13 Dec 2004

Issue number: 2

This Tech Note applies to Exedy clutch kit part number NSK-7130 (Nissan Patrol).

It has come to our attention that pedal graunch and an erratic pedal feel may be apparent after the fitment of this clutch kit. To overcome and rectify these problems, a self-aligning release bearing has been supplied with this clutch kit. This bearing will eliminate the possibility of misalignment, the prime cause of erratic pedal feel.

Note: misalignment is evident in some cases by red dust on the diaphragm tip and release bearing

PLEASE ENSURE THE NEW BEARING IS PRESSED ON SQUARELY AND WITH GREAT CARE

